


**Śruby z łbem grzybkowym
 i podsadzeniem**

Flachrundsrauben
 Mushroom head square neck bolts



d	M5	M6	M8	M10	M12	M16	M20	
d_k	13,5	16,55	20,65	24,65	30,65	38,8	46,8	
k	3,3	3,88	4,88	5,38	6,95	8,95	11,05	
f	4,1	4,6	5,6	6,6	8,75	12,9	15,9	
v	5,48	6,48	8,58	10,58	12,7	16,7	20,84	
b_{min}	$l \leq 125$	16	18	22	26	30	38	46
	$125 < l \leq 200$	22	24	28	32	36	44	52
	$l > 200$	-	-	41	45	49	57	65